



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Sep 22, 2025

Inspection Result: **PASSED**

Permit Number: PRFUP20250500

Property Address: 113 23RD AVE SE, PUYALLUP, WA 98372;

Contractor: PSE - POTELCO 5807 MILWAUKEE AVE Puyallup, WA 98372

To construct: 186065120- Work in ROW to restore 6x6 patch where down guy anchor was installed under previous permit PRFUP20231261. Per City Inspector from the 4/17/24 inspection report: "The east wing of the sidewalk approach needs to be replaced due to the new guy wire hold down install. The panel was painted out for restoration."

On this day we have inspected your construction for **Engineering Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: All work has been completed.

Corrections:

Sincerely,

Cheryl Trimble
Development Engineering Inspector
CTrimble@PuyallupWA.gov
(253) 290-9834