



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Oct 06, 2025

Inspection Result: **PARTIAL PASS**

Permit Number: PRCCP20250372

Property Address: 1015 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: JTM CONSTRUCTION 5900 AIRPORT WAY SOUTH, #110 SEATTLE, WA 98108 (206) 773-3360

To construct: SITE WORK ASSOCIATED W/COP PUBLIC SAFETY BDLG

On this day we have inspected your construction for **Engineering Daily Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Hydro tested the new south hydrant install. Tested @ 200psi for 1hr (PASSED).

Bag flushed hydrant from both ports for 5min. (heavy scaling in burlap bags was found.

*NOTE: Highly suggest! Existing fire main should be flushed once or twice a year around the entire complex. The scaling debris found in the line will clog the fire sprinkler heads in the building if a fire does break out.

Corrections:

Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Jason Little

Development Engineering Inspector

JLittle@PuyallupWA.gov

(253) 244-0387