BACKFLOW PREVENTION ASSEMBLY TEST REPORT



WATER PURVE	YOR Puyallup, City	of	ACCOUN	ACCOUNT #	
ASSEMBLY ID/FILE #/UTILITY DEVICE_#			Meter #		
NAME OF PREMISE 2902 Pioneer Way E Commercial Residential					
SERVICE ADDRESS 2902 Pioneer Way E Puyallup ZIP 98372					
CONTACT PERSON PHONE (253) 279-1892					
LOCATION OF ASSEMBLY North of building B in vault (Building B 6" fire)					
DOWNSTREAM PROCESS DCVA X RPBA PVBA OTHER_DC					
NEW INSTALL EXISTING REPLACEMENT REMOVED OLD SER.#					
APPROVED ASSEMBLY? YES \boxtimes NO \square PROPER INSTALLATION? YES \boxtimes NO \square					
MAKE OF ASSEMBLY Wilkins MODEL 350ASTDA SERIAL NO. 43105 SIZE 6"					
INITIAL	DCVA / RPBA	DCVA / RPBA	RPBA	PVBA / SVBA	
TEST	CHECK VALVE NO.1	CHECK VALVE NO.2	OPENED ATPSID	AIR INLET	
PASSED X	CLOSED TIGHT X	CLOSED TIGHT X	#1 CHECKPSID	OPENED AT PSID	
	LEAKED	LEAKED		DID NOT OPEN	
FAILED	1.5 PSID		AIR GAP OR:		
	CLEAN REPLACE PART	CLEAN REPLACE PART	CLEAN REPLACE PART	CHECK VALVE	
NEW DADTS				HELD AT PSID	
PARTS				LEAKED	
AND				CLEANED	
REPAIRS				REPAIRED	
TEST AFTER REPAIRS	CLOSED TIGHT	CLOSED TIGHT	RV EXERCISED	AIR INLET PSID	
PASSED	LEAKED	LEAKED	OPENED AT PSID		
FAILED	PSID	PSID	#1 CHECKPSID	CHK VALVEPSID	
AIR GAP INSPECTION: SUPPLY PIPE DIAMETER SEPARATION PASS FAIL					
DETECTOR METER READING					
LEFT SERVICE AS FOUND Isolation valve: Open X Closed SOV#1: Open Closed X SOV#2: Open X Closed					
REMARKS:					
Bypass Psi: Closed Tight Leaked LINE PRESSURE 45 PSI CONFINED SPACE?					
TESTERS SIGNATURE: CERT. NO. <u>B8319</u> DATE <u>08-14-25</u>					
TESTERS NAME PRINTED Braden (Richard) Stone TESTERS PHONE # 425-277-2888					
REPAIRED BY:		LIC N	NO	DATE	
FINAL TEST BY:					
CALIBRATION DATE 03-31-2025 GAUGE # 10201207 MODEL 845-5 SERVICE RESTORED YES NO					