



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Oct 23, 2025

Inspection Result: NOT READY

Permit Number: PRCTI20240333

Property Address: 1023 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: HOWARD S WRIGHT 415 1ST AVE N SEATTLE, WA 98109

To construct: Interior tenant improvements to construct new UPS ROOM of 2,223 s.f. and new BATTERY ROOM of 1,474 s.f. - CENTERIS VOLTAGE PARK *
REVISION (1) - 10/14/2025 - REPLACE NICKEL-ZINC BATTERIES WITH VRLA BATTERIES ENLARGING BATTER ROOM TO ACCOMMODATE NEW LAYOUT

On this day we have inspected your construction for **Frame Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: cancel per contractor.

Corrections:

1. framing of opening for electrical at battery room approved

Sincerely,

Shannon King

Building Inspector 2

ShannonK@PuyallupWA.gov

(253) 840-6684



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org