BACKFLOW PREVENTION ASSEMBLY TEST REPORT



WATER PURVEYOR Puyallup, City of			ACCOUNT #	
ASSEMBLY ID/FILE #/UTILITY DEVICE #			Meter #	
NAME OF PREMISE Job trailers			Commercial Residential	
SERVICE ADDRESS 1805 Industrial Pkwy			Puyallup ZIP 98371	
CONTACT PERSON_			PHONE (206) 507-4075	
LOCATION OF ASSEMBLY 47.20852° N, 122.30791° W				
DOWNSTREAM PROCESS DCVA				
NEW INSTALL EXISTING REPLACEMENT REMOVED OLD SER.#				
APPROVED ASSEMBLY? YES \boxtimes NO \square PROPER INSTALLATION? YES \boxtimes NO \square				
MAKE OF ASSEMBLY Apollo MODEL RPLF4A SERIAL NO. 252950 SIZE 2"				
INITIAL TEST	DCVA / RPBA		<u>RPBA</u>	PVBA / SVBA
		CHECK VALVE NO.2	OPENED AT 3.5 PSID	
PASSED X	CLOSED TIGHT X	CLOSED TIGHT X	#1 CHECK_ 7.0 PSID	OPENED AT PSID
	LEAKED	LEAKED		DID NOT OPEN
FAILED		PSID		
NEW	CLEAN REPLACE PART	CLEAN REPLACE PART	CLEAN REPLACE PART	CHECK VALVE HELD AT PSID
PARTS				LEAKED PSID
AND				
REPAIRS				CLEANED
TEST AFTER	CLOSED TIGHT	CLOSED TIGHT	RV EXERCISED	AIR INLET PSID
REPAIRS PASSED	LEAKED	LEAKED	OPENED ATPSID	1312
FAILED	PSID	PSID	#1 CHECKPSID	CHK VALVEPSID
AIR GAP INSPECTION: SUPPLY PIPE DIAMETER SEPARATION PASS FAIL				
DETECTOR METER READING LEFT SERVICE AS FOUND Isolation valve: Open				
REMARKS:				
Bypass Psi: Closed Tight Leaked LINE PRESSURE 65 PSI CONFINED SPACE?				
TESTERS SIGNATURE: CERT. NO. <u>B7730</u> DATE <u>11-14-25</u>				
TESTERS NAME PRINTED Ethan Paz TESTERS PHONE # 425-277-2888				
REPAIRED BY:		LIC N	NO	DATE
FINAL TEST BY: DATE				DATE
CALIBRATION DATE 12-31-2024 GAUGE # 06160827 MODEL 845-5 SERVICE RESTORED YES ☒ NO ☐				