City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Dec 01, 2025 Inspection Result: NOT READY

Permit Number: PRCTI20250558

Property Address: 401 15TH AVE SE, PUYALLUP, WA 98372;

Contractor: SELLEN CONSTRUCTION CO INC PO BOX 9970 SEATTLE, WA 98109-

9970 ABBOTT CONSTRUCTION 3408 1ST AVENUE SOUTH SEATTLE, WA

98134

To construct: Phase 0 will create new storage capacity and access points for hospital

staff prior to the full buildout of the expanded Kitchen. MULTICARE

GOOD SAMARITAN HOSPITAL KITCHEN PHASE 0

On this day we have inspected your construction for **Frame Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

1 1. Provide approved UL listing for fire wall.

innon King

- 2. Provide electrical final at time of frame inspection.
- 3. Remove sheetrock screws in upper deflection track.
- 4. Okay to one side sheetrock.
- 2 1. remove drywall at soffit to inspect framing of soffit as discussed with contractor.

Sincerely,

Shannon King



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

Building Inspector 2 ShannonK@PuyallupWA.gov (253) 840-6684