

Backflow Assembly Test Report

Made By Mako Assist on: 12/02/2025 at 12:29 PM

SANTA CONSTRUCTION SITE BROWN STONE

Water Authority: PUYALLUP WATER

Contact Name: NICK @ SANTA CONST.

Service Address: 707 39th Ave SE
Puyallup, WA 98374
United States

ASSEMBLY

Type: RP

Size: 3 INCH

Manufacturer: WILKINS

Model: 375

Serial Number: 168021

Geo Tag: 47.15534549374453
-122.28318023629677



DOMESTIC RPBA

TEST GAUGE

Name: MAKO MK5

Serial Number: 2AC19070168

Calibration Date: 2025-01-29



TEST RESULTS

Test Procedure Followed: USC Manual 10/ABPA

Relief Valve Opening Point (RV) (PSID):	2.3	RV Fully Opened?:	YES
Check Valve 1 (CV 1) (PSID):	8.6	CV 1 Held Tight?:	YES
Line Pressure (LP) (PSID):	86.0	CV 2 Held Tight?:	YES

COMMENTS

HAZARD- DOMESTIC RPBA
LOCATION- WEST SIDE OF BLDG INSIDE
INSULATED ENCLOSURE.

PASS

CERTIFIED BY:

Name: travis grant
Certificate #: B5889
Company: Grant Utilities Inc.
Phone: 4254492072
Email: travisgrant@me.com

