



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Jan 13, 2026

**Inspection Result:** NOT READY

**Permit Number:** PRPO20251253

**Property Address:** 707 39TH AVE SE, PUYALLUP, WA 98374;

**Contractor:** WALSH CONSTRUCTION CO. 315 FIFTH AVE S, SUITE 600 SEATTLE, WA 98104- (206) 547-4008

**To construct:** We are building the pool and spa at the Wesley Bradley project. Their project permit number is PRCNC20240424. This permit is for the pool and spa associated with this project. - WESLEY HOMES, BRADLEY PARK

On this day we have inspected your construction for **Foundation/Rebar Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** 1. Have proper clearance from rebar to gravel.

2. Provide rebar around drains and light fixtures installed as designed on the approved print.

3. Provide minimum clearance from rebar to side wall.

4. Have plumbing finished and on test.

**Corrections:**

- 2 1. Have proper clearance from rebar to gravel.
2. Provide rebar around drains and light fixtures installed as designed on the approved print.
3. Provide minimum clearance from rebar to side wall.
4. Have plumbing finished and on test.

Sincerely,



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)



James LaVergne

[JLaVergne@PuyallupWA.gov](mailto:JLaVergne@PuyallupWA.gov)

(253) 841-5590