



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Jan 13, 2026

**Inspection Result:** NOT READY

**Permit Number:** PRCTI20240438

**Property Address:** 1023 39TH AVE SE, PUYALLUP, WA 98374;

**Contractor:** HOWARD S. WRIGHT CONSTRUCTION CO. 415 1ST AVE #400 N  
SEATTLE, WA 98109

**To construct:** Installation of exterior wall penetration assemblies and supplementary metal stud framing and steel headers. BLDG ONLY \* REVISION (1) - 7/25/2024 - ADDING ONE NEW WALL PENETRATION.

On this day we have inspected your construction for **Building Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:**

**Corrections:**

Sincerely,



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)



James LaVergne

[JLaVergne@PuyallupWA.gov](mailto:JLaVergne@PuyallupWA.gov)

(253) 841-5590