



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Jan 16, 2026

**Inspection Result:** FAILED

**Permit Number:** PRMU20230881

**Property Address:** 707 39TH AVE SE, Unit: D, PUYALLUP, WA 98374;

**Contractor:** Anthony Mizin 315 fifth Ave S. Suite 600 Seattle, WA 98104 WALSH CONSTRUCTION CO. 315 FIFTH AVE S, SUITE 600 SEATTLE, WA 98104- (206) 547-4008

**To construct:** As part of the Phase 2 development of Wesley Bradley Park, - Group R2 w/ 3 stories Type VA over Type 1A concrete garage. This project has 67 dwelling units. - WESLEY HOMES BRADLEY PARK PH 2 - BROWNSTONE \* REVISION (1) - 6/24/2025 - ENERGY CODE CALS, EV CAR LOCATION AND GARAGE AND DAS SYSTEM LOCATION.

On this day we have inspected your construction for **Frame Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** framing inspection for 2 walls at east side of building at covered area by main entrance.  
1 ; provide positive attachment at top plates to main building.  
2 ; seal top pf chase at both exterior columns.

**Corrections:**

Sincerely,

A handwritten signature in black ink that reads "Shannon King". The signature is fluid and cursive, with "Shannon" on the left and "King" on the right, connected by a line.

Shannon King  
Building Inspector 2



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371  
(253) 864-4165  
[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

ShannonK@PuyallupWA.gov  
(253) 840-6684