



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Jan 30, 2026

**Inspection Result:** NOT READY

**Permit Number:** PRCTI20240784

**Property Address:** 1023 39TH AVE SE, PUYALLUP, WA 98374;

**Contractor:** HOWARD S WRIGHT 415 1ST AVE N SEATTLE, WA 98109


**To construct:** Interior tenant improvement to construct UPS & Battery Rooms totaling 1,753 sf - CENTERIS SCALE MATRIX UPS & BATTERY ROOM TENANT IMPROVEMENT \* REVISION (1) - 10/30/2024 - ADD HYDROGEN DETECTION SYSTEM TO BATTERY ROOM

On this day we have inspected your construction for **Engineering Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** See civil permit PRCCP20240183. Need punchlist completed prior to final for this permit.

**Corrections:**

Sincerely,



Jason Little  
Development Engineering Inspector



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

JLittle@PuyallupWA.gov

(253) 244-0387