

City of Puyallup **Engineering Division** 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

## **INSPECTION REPORT**

Date of Inspection:	Jan 17, 2022	Inspection Result:	PARTIAL PASS
Permit Number: Property Address:		;	
	WA 98001	CTION CO. <no al<="" street="" th=""><th>DDRESS&gt; AUBURN,</th></no>	DDRESS> AUBURN,
TO CONSTRUCT:	SEWER EXTENSION		

On this day we have inspected your construction for **Engineering Daily Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** RW Scott dug up the north side of ssmh#2. the pipe just out side of MH has back fall of 1.3%. 3% of fall through MH. per the plans the fall through the MH should be 2.5% (0.10'). south side (inlet) falls at 1.25%. RW Scott believes the MH settled causing the belly in the line.

Corrections:

Sincerely,

Jeff Hill Engineering Tech IV Jhill@PuyallupWA.gov (253) 841-5424