### City of Puyallup

#### **Building Division**

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

#### **INSPECTION REPORT**

Date of Inspection: Feb 04, 2022 Inspection Result: FAILED

Permit Number: B-21-0544

**Property Address:** 4423 S MERIDIAN;

Contractor: PROBUILD CONSTRUCTION 12112 92ND AVE CT E PUYALLUP, WA

98373 Alex Rodriguez 12112 92ND AVE CT E SOUTH HILL, WA 98373

(253) 844-7547

To construct: TI ~ TANDOORI GRILL

BLDG/PLUMB/MECH

On this day we have inspected your construction for **Grease Interceptor Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:** No compaction on ditches, cast iron sewer needs to be added, and site needs to be cleaned up prior to rain.

#### **Corrections:**

1 No compaction on ditches, cast iron sewer needs to be added, and site needs to be cleaned up prior to rain.


Sincerely,



## City of Puyallup

# **Building Division**

333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org



Jason Little Engineering Tech IV JLittle@PuyallupWA.gov (253) 435-3636