

City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

| Date of Inspection: | May 03, 2022 | Inspection Result: | FAILED |
|-------------------------------------|--|-------------------------|----------------|
| Permit Number: Property Address: | | | |
| Contractor: | MOUNTAIN CONSTRU 98409 | CTION INC. 7457 S MADIS | SON TACOMA, WA |
| To construct: | TI ~ MODIFY BATHROOM; INCREASE KITCHEN; ADD STORAGE; | | |
| | REMOVE CLASSROOM & OFFICE. ~ STEP BY STEP | | |
| | BLDG/MECH/PLUMB | | |
| | | | |

On this day we have inspected your construction for **Energy (Insulation) Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

1 1; complete all insulation at exterior walls and insulate hotwater supply lines as discussed with contractor.

Sincerely,

n King

Shannon King Building Inspector 2 ShannonK@PuyallupWA.gov (253) 840-6684



City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org