



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Jun 03, 2022

Inspection Result: **FAILED**

Permit Number: PRUSR20220749

Property Address: 925 S MERIDIAN, PUYALLUP, WA 98371;

Contractor: MR ROOTER PLUMBING 2000 S 116TH ST SEATTLE, WA 98168

To construct: Spot repair of sewer line from outside front door of business to inside front door

On this day we have inspected your construction for **Engineering Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: 1. Concrete debris needs to be cleaned up.
2. Concrete edges should have been saw cut prior to pour.
3. C/O's at the building are about an inch low.
4. Call for an on site meeting.

Corrections:

- 1 1. C/O needs to say sewer.
2. Concrete debris needs to be cleaned up.
3. Concrete edges should have been saw cut prior to pour.
4. C/O's at the building are about an inch low.
5. Call for an on site meeting.

Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Jason Little
Engineering Tech IV
JLittle@PuyallupWA.gov
(253) 435-3636