



100 Stall Gain Proposed Parking w/ reduced islands	100 Stall Gain Parking to City Code	Existing Tree Information per Arborist Report	
1 removed	2 removed		Trees with >36" DBH Good condition
5 removed	13-14 removed		Trees with 24" to 36" DBH Good condition
0 removed	0 removed		Trees with 24"+ DBH Fair to Poor condition
18 removed	23-25 removed		Trees 15" to 24" DBH Varying condition
			Trees to be removed, Reference Sheet L1.01

