



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Jul 28, 2022

Inspection Result:

**PASSED W/
CONDITIONS**

Permit Number: PRUSR20221164

Property Address: 110 9TH ST SW, PUYALLUP, WA 98371;

Contractor: HARTS SERVICES 3510 S PINE ST TACOMA, WA 98409

To construct: Water Line Repair

On this day we have inspected your construction for **Comment Engineering Div Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Crew reinstalled a new poly line. Okay to backfill. Keep big rocks off pipe. Asked crew to install foam where the poly exits the sleeve at a 90deg. bend. Possible rubbing overtime creating a leak. Also notified crew about the sidewalk replacement. No tunneling underneath the sidewalk. Also notified the crew about needing a ROW permit next time they enter. Also notified the crew about not using barbed fittings at the house. It will create a leak over time. Will be back to look at final clean up.

Corrections:

Sincerely,



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

A handwritten signature in black ink, consisting of a large, loopy initial 'J' followed by several vertical, wavy lines that resemble the letters 'LITTLE'. A horizontal line extends from the right side of the signature.

Jason Little
Engineering Tech IV
JLittle@PuyallupWA.gov
(253) 435-3636