



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Jul 29, 2022

Inspection Result: **FAILED**

Permit Number: PRUSR20221164

Property Address: 110 9TH ST SW, PUYALLUP, WA 98371;

Contractor: HARTS SERVICES 3510 S PINE ST TACOMA, WA 98409

To construct: Water Line Repair

On this day we have inspected your construction for **Engineering Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Exposed soil needs to be stabilized from runoff (rock or seed and straw). Sidewalk panel needs to be sawcut, removed, ditch dug up and compacted with jumpin jack, rock installed for base and poured back.

Corrections:

Sincerely,

Jason Little
Engineering Tech IV
JLittle@PuyallupWA.gov



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

(253) 435-3636