

City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

INSPECTION REPORT

| Date of Inspection: | Sep 06, 2022 | Inspection Result: | NOT READY | |
|-------------------------------------|--|----------------------|-----------|-----|
| Permit Number: Property Address: | B-20-0993 3213 WILDWOOD PARK | DR, PUYALLUP, WA 983 | 74; | |
| | PEASE & SONS PO BOX 10-CLASSRM ADDITION 20-0612 CIVIL* | | | *E- |

On this day we have inspected your construction for **Mechanical Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: 1. cancelled by contractor on site

Corrections:

Mechanical
Mechanical room - Complete Sample tube - verify correct installation
Duct detector - in mechanical room not working
Lobby areas floor 1-3 reinspection required - will require removal of subsancial ceiling tile for inspection
Provide sealed - revised plans from ERO for duct replacement in the lower level; reference emails
Damper functional test completee 7 devices at the 2nd and 3rd floors

Sincerely,

annon King

Shannon King



City of Puyallup Building Division 333 S. Meridian, Puyallup, WA 98371 (253) 864-4165 www.cityofpuyallup.org

Building Inspector 2 ShannonK@PuyallupWA.gov (253) 840-6684