EMERALD FIRE, LLC Fire Sprinkler Specialists

BACKFLOW PREVENTION ASSEMBLY TESTING REPORT

☐ NEW INSTALLATION CITY USE ONLY SERVICE NO. 4 SIZE MANUFACTURER Derringer 30 Ames DEVICE NO. OWNER/CONTROLLER Step by Step METER NO. OWNER'S ADDRESS SERVICE ADDRESS 3303 8th Ave se Puyallup, wa. 98372 LOCATION OF DEVICE Sprinkler riser room (new building). HAZARD ISOLATED POTABLE WATER RRIGATION FIRE BOILER D.C.D.A. P.V.B.A. S.V.B.A. AIR GAP R.P.B.A R.P.D.A. D.C.V.A. IS DEVICE INSTALLED PROPERLY? ✓ ES NO - COMMENTS REDUCED PRESSURE ASSEMBLY P.V.B.A. / S.V.B.A **INITIAL TEST** AIR INLET CHECK DOUBLE CHECK #1 CHECK CHECK #1 PASSED PRESS DROP 2.2 PRESS DROP **OPENED AT** TIGHT INITIAL **FAILED** psid RELIEF VALVE **TEST** LEAKEL OPENED AT DATE: RESULTS min 2 psid /5 / 22 BUFFER CHECK #2 **PSID PSID** A-B= 1.7 **TIGHT** min 3 psi DID NOT FAILED SYSTEM PSI psid **RELIEF VALVE** 83 LEAKED OPEN PASS FAII COMMENTS Found off left off; building under construction. REPAIRS AND/OR **PARTS** REDUCED PRESSURE ASSEMBLY P.V.B.A. / S.V.B.A FINAL TEST CHECK DOUBLE CHECK AIR INLET CHECK #1 #1 CHECK **PASSED** PRESS DROP (A) OPENED AT PRESS DROP **TIGHT** TEST psid **RELIEF VALVE AFTER** DATE: OPENED AT REPAIRS CHECK #2 min 2 psid BUFFER **PSID PSID** TIGHT A-B= psid min 3 psi IN COMPLETING AND SUBMITTING THIS TEST REPORT, THE TESTER CERTIFIES THAT THE ASSEMBLY HAS BEEN TESTED AND MAINTAINED IN ACCORDANCE WITH ALL APPLICABLE RULES AND REGULATIONS OF THE CITY OF WASHINGTON. ,28 DETECTOR METER READING 0000010 GAUGE CALIBRATION DATE 2 Shane Foss TESTER NAME (PRINTED) CERTIFICATION # TESTER SIGNATURE 03110746 Emerald Fire LLC GAUGE # COMPANY 253-857-2056 11021 Cramer Road, KPN Gig Harbor WA 98329 PHONE # ADDRESS

(SIGNATURE OF OWNER OR REPRESENTATIVE OF OWNER)

REPORT RECEIVED BY:

ERVICE RESTORED

Revised 4/29/1999