



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Oct 03, 2022

Inspection Result: **FAILED**

Permit Number: PRCTI20220498

Property Address: 1201 39TH AVE SW, PUYALLUP, WA 98373;

Contractor: FERGUSON CONSTRUCTION, INC - JUSTIN ARMSTRONG 13810 SE EASTGATE WAY, STE 110 BELLEVUE, WA 98005 (425) 974-8400

To construct: 801 SF Mezzanine Locker Room Addition, Ground Floor Remodel

On this day we have inspected your construction for **Combination Frame And Rough In Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments:

Corrections:

1. complete all R/I prior to next inspection
2. provide electrical cover inspection prior to next inspection
3. have all plumbing on test at time of next inspection
4. NOT READY

Sincerely,

Shannon King

Building Inspector 2

ShannonK@PuyallupWA.gov

(253) 840-6684



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org