


THE APPROVED CONSTRUCTION PLANS AND ALL DOCUMENTS MUST BE POSTED ON THE JOB AT ALL INSPECTIONS IN A VISIBLE AND READILY ACCESSIBLE LOCATION.

Puyallup, WA Store #2403 Damaged Insulation Extents (08.11.22)

Reviewed 10/03/2022 DL Subject to field inspectors approvals.



Legend:

- ## Indicates photo summary items # locations
- Moist insulation extents, as interpreted through IR scans and Tramex readings (Total = 1400 sq ft)