



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Date Issued 19 Mar 2024
Permit Number PRCTI20240431
Contractor's Name GOODMAN HOME SERVICES, LLC.

INSPECTIONS REQUIRED

Planning Final Inspection - Planning Final Inspection

Fire Final Inspection - Fire Final Inspection

Engineering Final Inspection - Engineering Final Inspection

Wallboard / Drywall Inspection - Wallboard / Drywall Inspection

Shear Wall Inspection - Shear Wall Inspection

Roof Sheathing Inspection - Roof Sheathing Inspection

Medical Gas Inspection - Medical Gas Inspection

Light Test For Grease Duct Inspection - Light Test For Grease Duct Inspection

Hydrostatic Test 200Lbs 2Hrs - Hydrostatic Test 200Lbs 2Hrs

Hydronic Piping Inspection - Hydronic Piping Inspection

Frame Inspection - Frame Inspection

Foundation/Rebar Inspection - Foundation/Rebar Inspection

Footing/Setback Inspection - Footing/Setback Inspection

Firewall/Firestop Inspection - Firewall/Firestop Inspection

Fire Or Smoke Damper Inspection - Fire Or Smoke Damper Inspection

Exit Lighting Test Inspection - Exit Lighting Test Inspection

Exhaust/Vent Fans Inspection - Exhaust/Vent Fans Inspection



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Exhaust Hood Inspection - Exhaust Hood Inspection

Building Final Inspection - Building Final Inspection

Ceiling Grid/T-Bar Inspection - Ceiling Grid/T-Bar Inspection

Combination Frame And Rough In Inspection - Combination Frame And Rough In Inspection

Comment Building Div Inspection - Comment Building Div Inspection

Comment Engineering Div Inspection - Comment Engineering Div Inspection

Cover Inspection/Thrust Blocks Inspection - Cover Inspection/Thrust Blocks Inspection

Emergency Radio Test Review Inspection - Emergency Radio Test Review Inspection

Energy (Insulation) Inspection - Energy (Insulation) Inspection

Refrigeration Line Test Inspection - Refrigeration Line Test Inspection

Slab/Insulation Inspection - Slab/Insulation Inspection