



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Nov 15, 2024 **Inspection Result:** **PARTIAL PASS**

Permit Number: PRCCP20240215

Property Address: 325 TODD RD NW, PUYALLUP, WA 98371;

Contractor: PENNON CONSTRUCTION CO. INC. 9750 3RD AVE NE SEATTLE, WA 98115 Sean Ewing 9750 3rd Ave NE, Ste 250, Pennon Construction Seattle, WA 98115 (206) 430-2537

To construct: THE PROPOSED PROJECT IS FOR A NEW OPERATIONAL TRAINING CENTER. The project is composed of the main OTC building, and Outdoor Training area. It will be used as a vocational school for UTILITY FIRST RESPONDERS AND construction trades.

On this day we have inspected your construction for **Engineering Daily Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Water main and fire line passed pressure test and valve check. FDC still to be tested.

Sewer video testing:

MH 2 to 1 ponding areas: 7.5' to 15', 37'-45', 52'-59', 77'-97', 120'-127', 135'-140', 159'-176', 230'-237', 262'-266' start of debris in the line, 290'-296', 300'-335' dye did not make it to the end. Over 10% ponding per section 406.4 note 2 of the city standards. the mandrill passed

MH2 to 3 ponding areas: 21'-26', 44'-51', 64'-67', 78'-82', 91'-94', 101'-117' (1/2" belly at 107.4'), 135'-139', 149'-152', 164'-168', 184'-217', 223'-227', 235'-238', 248'-259', 269'-279', 287'-292'. over 10% of the ponding and one belly at a 1/2". Mandrill passed.

MH4 to 3 ponding areas: Camera starts at 7.5' looks to be ponding, 22'-27', 36'-43', 78'-84', 92'-102', 107'-112', 121'-123'. over 10% ponding mandrill passed.

MH4 to 5 ponding areas: Camera starts at 7.5' looks to be ponding, 26'-36', 56'-71', 84'-89', 106'-117', 127'-134'. Over 10% ponding. Mandrill passed.

MH6 to 5 ponding areas: 22'-27', 67'-76', 85'-91', 173'-181'. over 10% ponding mandrill passed.



City of Puyallup

Engineering Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

MH 7 to 6 Passed ponding under 10% No 1/2" bellies mandrill passed.

MH 7 to 8 Passed ponding just under 10% no 1/2" bellies mandrill passed.

MH 9 to 8 ponding areas: 18'-26', 43'-45', 54'-77', 85'-93', 147'-153', 170'-172', 180'-185', 227'- 244' debris. Over 10% ponding mandrill passed.

Air tests SSMH 1-2 pass. SSMH 6-7 pass. SSMH7-8 pass.

After ponding is fix a video test, mandrill test, and pressure test will be required.

Corrections:

- 1 Television Inspection Acceptance Criteria:
 1. Any ponding within a pipe shall be less than one-half inch (1/2") in depth.
 2. The total accumulated ponding length, regardless of depth, from manhole to manhole shall be less than ten (10) percent of the total length from manhole to manhole.Any sewer pipe that exceeds either of the above acceptance criteria will be rejected and require repair and/or replacement by the Contractor.

Sincerely,

Jeff Hill
Development Engineering Inspector
Jhill@PuyallupWA.gov
(253) 204-5633