



Stormwater > Online Inspection > FC Site Report column

FC Site Report



Creator **Sean Sagraves**



Created **Dec 09, 2025, 11:07**



Last updated **Dec 11, 2025, 09:10**

Project Name/Number/Seq - Online Inspection 685097 T No value

FC/Support Type/Cat  David V Onsite Support  No value

PC/Structure  No value T No value {

Precaster - T No value

Date QC Completed  No value

Scheduled Delivery Date - Wed, Dec 10, 2025

Location - T No value T No value 501 2nd St NW, Puyallup, WA, USA

SE - T No value

Customer Contacts

Name	Email	Phone number
T No value	T No value	T No value

- Confined Space Entry?**
- QC Complete matches Fab**

FC notes and inspection dates

Inspected three SFCB, all filters are installed correctly.
media looks good.
These units are functioning as intended.









