



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Mar 24, 2026 **Inspection Result:** **FAILED**

**Permit Number:** PRMH20251523

**Property Address:** 1601 39TH AVE SE, PUYALLUP, WA 98374;

**Contractor:** ELITE MECHANICAL SERVICES, LLC 2625 REINHARDT LN NE, SUTIE F LACEY, WA 98516 (360) 489-0717

**To construct:** Demo: HP-1, HP-2, HP-3 Disconnect comm wiring Disconnect heat pump's from existing curbs Crane heat pump's off roof Haul off equipment and dispose of per EPA standards Furnish and Install New: Daikin Heat Pump RTU's 460v/3ph Electric back up heat Crane curb adapters to roof Secure curb adapters to existing roof curbs Crane heat pump's on to curb adapters Connect comm wiring Condensate p traps Economizers Start and test heat pump's Mechanical permit Alt 1: Replace HP-4,5,6 - CHILD DEVELOPMENT CENTER PIERCE COLLEGE

On this day we have inspected your construction for **Mechanical Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:**

**Corrections:**

- 1 1. Duct detector inspection and test required.
2. Fire inspection required.
3. Provide approved plans on site for inspection as to scope of work being performed.
- 2 Duct detector inspection failed. ( r.t.u. did not shut down)

Sincerely,



City of Puyallup

---

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

Shannon King

Building Inspector 2

[ShannonK@PuyallupWA.gov](mailto:ShannonK@PuyallupWA.gov)

(253) 840-6684