



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Apr 03, 2026

Inspection Result:

**PASSED W/
CONDITIONS**

Permit Number: PRMH20251340

Property Address: 1015 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: MACDONALD/MILLER FAC SOL INC PO BOX 47983 SEATTLE, WA
98106

To construct: REPLACE 20-TON HEAT PUMP, REUSING THE EXISTING CURB FROM THE
CURRENT UNIT. - SHBTC BLDG C

On this day we have inspected your construction for **Mechanical Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

Comments: Remove pallets from rooftop

Corrections:

Sincerely,




City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org



James LaVergne

JLaVergne@PuyallupWA.gov

(253) 841-5590