

PRSC20260387

Welcome!
(253) 649-1500 or (800) 330-1844



[Help](#)

[Home](#) [Search](#) [Create](#)

Logged in as: Ernest Julian Fernandez Collections (0) Cart (0) [Account Management](#) [Logout](#)

Record OSSD2026-000043:
OSS Decommissioning
Record Status: Pending

[Add to cart](#)
[Add to collection](#)

[Record Info ▾](#) [Payments ▾](#) [Custom Component](#)

Links:
[OnlineRME](#)
[Asbuilt Lookup](#)
[Report of System Status Inspection](#)

Work Location

302 TODD RD NE, Puyallup, 98372 *

Record Details

Applicant:

Ernest Fernandez
AUU-INC
Mobile Phone: 2539882449
ej@auuinc.com
Billing
P.O. Box 309
Sumner, WA, 98390
United States

Owner:

FERNANDEZ ERNEST & FERNANDEZ CATHERINE *

► More Details

[Copy Record](#)

Tacoma-Pierce County Health Department

TANK PUMPING REPORT

PRSC20260387

Site Name:

Location: 302 TODD RD NE
Puyallup
Tax ID: 0420222028
Use:

Service Company:

Drain-Pro, Inc.
PO Box 100
Puyallup, WA 98372
253-926-5586

Serviced: 03/26/2026 by: Brandon Lewis

Submitted 03/30/2026 by: Dana Malarcher

Dump Location: King County Metro Wastewater Treatment Plant

Jurisdiction ID: ON2026-00142

COMMENTS

Pump for Demo.

TANK: Septic Tank - 1 Compartment

Tank Pumped:	YES	
Total Gallons pumped from tank (Number only, no text):	750	
Tank Size (Gallons)(Number only, no text):	750	
Tank depth below grade (inches):	0	
Effluent level within operational limits (if NO explain in comments):	YES	
Effluent returning back into tank after pumping:	NO	
Access Risers installed to grade (N/A if not present):	N/A	
Tank Construction Material:	Concrete	
Tank Condition Good:	YES	
Baffles in good condition (N/A if not present):	YES	
Effluent screen cleaned (N/A if not present):	N/A	
Effluent surfacing around site components (N/A if not checked):	NO	
Tank abandoned after pumping:	YES	
Were repairs made to the Tank or Tank Components? (if YES explain in comments):	NO	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	12	

TANK: Septic Tank - 1 Compartment

Tank Pumped:	YES	
Total Gallons pumped from tank (Number only, no text):	750	
Tank Size (Gallons)(Number only, no text):	750	
Tank depth below grade (inches):	0	
Effluent level within operational limits (if NO explain in comments):	YES	
Effluent returning back into tank after pumping:	NO	
Access Risers installed to grade (N/A if not present):	N/A	
Tank Construction Material:	Concrete	
Tank Condition Good:	YES	
Baffles in good condition (N/A if not present):	YES	
Effluent screen cleaned (N/A if not present):	N/A	
Effluent surfacing around site components (N/A if not checked):	NO	
Tank abandoned after pumping:	YES	
Were repairs made to the Tank or Tank Components? (if YES explain in comments):	NO	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	10	

This report indicates certain characteristics of the onsite sewage system at the time of visit. In no way is this report a guarantee of operation or future performance.