



City of Puyallup

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

## INSPECTION REPORT

**Date of Inspection:** May 20, 2026

**Inspection Result:** **FAILED**

**Permit Number:** PRPL20260722

**Property Address:** 401 15TH AVE SE, PUYALLUP, WA 98372;

**Contractor:**

**To construct:** Scope of Work:

This project involves the installation of a 1/2" Reduced Pressure Backflow Assembly (RPBA) under the counter to serve a new commercial coffee machine. The RPBA will be installed in compliance with local plumbing code requirements for cross-connection control and will be accessible for inspection, testing, and maintenance.

The RPBA will be connected to an existing 3/8" angle stop cold water supply using an approved transition fitting to upsize to 1/2". The installation will include:

- Installation of the 1/2" Watts LF009QT RPBA with proper clearance.
- Installation of an air gap on the RPBA relief vent.
- Routing of the air gap discharge (drain) line to the nearest approved drain receptor, such as a floor sink or hub drain.
- All work will comply with UPC, as well as local amendments.

The installation is limited to the connection of the coffee machine and related components. No other modifications to the plumbing system are included in this scope.

On this day we have inspected your construction for **Plumbing Final Inspection** and we find the following result of the inspection. If there are any questions, please contact the inspector below.

**Comments:**

**Corrections:**



City of Puyallup

---

**Building Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

- 1 provide backflow cert. prior to plumbing final inspection approval.

Sincerely,

Shannon King  
Building Inspector 2  
[ShannonK@PuyallupWA.gov](mailto:ShannonK@PuyallupWA.gov)  
(253) 840-6684