



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

INSPECTION REPORT

Date of Inspection: Jun 16, 2026

Inspection Result: **NOT READY**

Permit Number: PRCTI20260575

Property Address: 1023 39TH AVE SE, PUYALLUP, WA 98374;

Contractor: HOWARD S WRIGHT 415 1ST AVE N SEATTLE, WA 98109

To construct: Construct interior 2,424 s.f. expansion of existing server room. -
CENTERIS, DATA CENTER

On this day, we have inspected your construction for **Frame Inspection** and we find the following result of the inspection. If you have any questions, please contact the inspector below.

Comments: cancel per contractor.

Corrections:

- 1 complete framing details of 3rd floor non rated shaft wall assembly at top track of wall.

Sincerely,

Shannon King

Shannon King

Building Inspector 2

ShannonK@PuyallupWA.gov

(253) 840-6684