



City of Puyallup

---

**Engineering Division**

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

[www.cityofpuyallup.org](http://www.cityofpuyallup.org)

## INSPECTION REPORT

**Date of Inspection:** Jun 25, 2026

**Inspection Result:** **PASSED**

**Permit Number:** PRFUP20260420

**Property Address:** 727 SHAW RD, Unit: A, PUYALLUP, WA 98372;

**Contractor:** PSE - POTELCO 5807 MILWAUKEE AVE Puyallup, WA 98372

**To construct:** 185013450- WORK IN ROW TO REMOVE OH TRANSFORMER ON P01 AT  
GRID #568024-156391.

On this day, we have inspected your construction for **Job Start Inspection** and we find the following result of the inspection. If you have any questions, please contact the inspector below.

**Comments:** K&D arrived performed traffic control. The TCP lane configuration was outdated, so they had to get an arrow board for the west side of the intersection. Two Puyallup officers were on site to assist with traffic flow. Potelco removed a transformer and wrecked out temporary power cable.

Note: Request inspection to close once all work has been completed.

**Corrections:** See comments.

Sincerely,

# Cheryl Trimble

Cheryl Trimble

Engineer Technician III

[CTrimble@PuyallupWA.gov](mailto:CTrimble@PuyallupWA.gov)

(253) 290-9834