



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Date Issued 14 Aug 2026
Permit Number PRCTI20260913
Contractor's Name MCKINSTRY CO.

INSPECTIONS REQUIRED

Planning Final Inspection - Planning Final Inspection

Fire Final Inspection - Fire Final Inspection

Plumbing Final Inspection - Plumbing Final Inspection

Mechanical Final Inspection - Mechanical Final Inspection

Engineering Final Inspection - Engineering Final Inspection

Wallboard / Drywall Inspection - Wallboard / Drywall Inspection

Underfloor Inspection - Underfloor Inspection

Shear Wall Inspection - Shear Wall Inspection

Re-Roof Inspection - Re-Roof Inspection

Plumbing Rough In Inspection - Plumbing Rough In Inspection

Plumbing Below Slab Inspection - Plumbing Below Slab Inspection

Mechanical Rough In Inspection - Mechanical Rough In Inspection

Hydrostatic Test 200Lbs 2Hrs - Hydrostatic Test 200Lbs 2Hrs

Gas Test Inspection - Gas Test Inspection

Frame Inspection - Frame Inspection

Foundation/Rebar Inspection - Foundation/Rebar Inspection

Footing/Setback Inspection - Footing/Setback Inspection



City of Puyallup

Building Division

333 S. Meridian, Puyallup, WA 98371

(253) 864-4165

www.cityofpuyallup.org

Firewall/Firestop Inspection - Firewall/Firestop Inspection

Fire Or Smoke Damper Inspection - Fire Or Smoke Damper Inspection

Exhaust/Vent Fans Inspection - Exhaust/Vent Fans Inspection

Erosion And Sediment Inspection - Erosion And Sediment Inspection

Building Final Inspection - Building Final Inspection

Block Wall Rebar Inspection - Description

Ceiling Grid/T-Bar Inspection - Ceiling Grid/T-Bar Inspection

Comment Building Div Inspection - Comment Building Div Inspection

Comment Engineering Div Inspection - Comment Engineering Div Inspection

Emergency Radio Test Review Inspection - Emergency Radio Test Review Inspection

Energy (Insulation) Inspection - Energy (Insulation) Inspection

Refrigeration Line Test Inspection - Refrigeration Line Test Inspection

Slab/Insulation Inspection - Slab/Insulation Inspection