

PHOTOGRAPHS.....Harris building #2

Photographs start at south end of horse stalls and rotate clockwise around the building.

01...Barn door reinstalled at end of horse stalls.

02...please remove

03...shows typical windows

04...remove

05...shows two doors that are typical of doors replaced with original solid slabs.

06...remove

07...another original door.

08...three more windows

09...unpainted Roman brick (rare in Puyallup) and one original window (cracked)

10...front showing original store front.

11...Eagles side

12...Horse stalls

13...dog run

14 ...shower

15 ...terrazzo floor to be retained ...typical.

Other points of interest, not shown, are the two Harris offices.

Interior layout is mostly original because dividing walls are block.