



Phase I Environmental Site Assessment

Toyota of Puyallup

1400 River Road

Puyallup, Washington

Prepared for

KLS 1400, LLC

March 3, 2017

19267-00

PAGES 1-4 OF
1400 + PAGE REPORT

Full Report Available
@ Toyota of Puyallup.

[Handwritten signature]



HARTCROWSER

Phase I Environmental Site Assessment

Toyota of Puyallup

1400 River Road

Puyallup, Washington

Prepared for

KLS 1400, LLC

March 3, 2017

19267-00

Prepared by

Hart Crowser, Inc.

Anne Conrad, MS, LG

Geochemist

Anne.Conrad@hartcrowser.com

Julie K. W. Wukelic

Principal Engineer

Julie.Wukelic@hartcrowser.com

MARISSA GOODMAN

Environmental Engineer

Marissa.goodman@hartcrowser.com

Contents

1.0 EXECUTIVE SUMMARY OF FINDINGS	1
1.1 Summary of Historical Findings	1
1.2 Summary of Environmental Database Findings	1
1.3 Summary of Site Inspection Findings	2
1.4 Conclusions	2
1.4.1 RECs	3
1.4.2 Historical RECs	3
1.4.3 Controlled RECs	3
2.0 INTRODUCTION	3
2.1 Purpose and Involved Parties	4
2.2 Scope of Work	4
2.3 Data Gap Analysis	4
2.4 Assumptions, Limitations, and Exceptions	4
2.5 Special Terms and Conditions	5
2.6 User Reliance	5
3.0 PROPERTY OVERVIEW	5
3.1 Property Ownership and Location	5
3.2 Current Use and Property Description	6
3.3 Adjoining Site Use and Description	6
4.0 PROPERTY BACKGROUND/OPERATING HISTORY	6
4.1 Surrounding Sites	7
4.2 Historical Stations	7
4.3 Aerial Photographs	8
4.4 Topographic Maps	10
4.5 City Directories	10
4.6 Fire Insurance Maps	12
4.7 Public Agency Permits and Records	12
4.8 Written Documentation	13
4.9 Interviews	14
5.0 ENVIRONMENTAL SETTING	14
5.1 Regional Physiographic Conditions	14
5.2 Soil Conditions	15
5.3 Geologic Conditions	15
5.4 Surface Water and Groundwater Characteristics	15

6.0 RESULTS OF ON-SITE INSPECTION	15
6.1 Site Reconnaissance Observations	16
6.1.1 The Property	16
6.1.2 Adjoining Site and Vicinity Observations	17
6.2 Interviews	18
7.0 RESULTS OF REGULATORY AGENCY DATABASE LIST REVIEW	18
7.1 Property	20
7.2 Adjoining Sites	20
7.2.1 Eastern Adjoining Site – 1124 River Road North	20
7.2.2 Eastern Adjoining Site – 1114 River Road North	20
7.2.3 Western Adjoining Site – 1410 15th Street NW	20
7.2.4 Western Adjoining Site – 1502 River Road	20
7.3 Surrounding Sites	21
7.4 Orphan Sites	22
8.0 CONCLUSIONS AND RECOMMENDATIONS	22
9.0 ENVIRONMENTAL PROFESSIONALISM STATEMENT	22
10.0 REFERENCES	23

FIGURES

- 1 Vicinity Map
- 2 Site Plan

APPENDIX A

Site Reconnaissance Photographs

APPENDIX B

Historical Documentation: Sanborn Maps, Aerial Photographs, and City Directories

APPENDIX C

EDR Report

APPENDIX D

Previous Environmental Reports

APPENDIX E

Resumes

APPENDIX F

Hart Crowser Standard Terms and Conditions